

<b>Observation Number:</b>	201908704
<b>Originator:</b>	
<b>Date Created:</b>	25-Apr-2019
<b>Business Unit:</b>	Consulting
<b>Business Group:</b>	Resilient Environments
<b>Project/Office:</b>	RE - East US
<b>Sub Business Group:</b>	Americas
<b>Site/Office Name:</b>	Beltsville, MD
<b>Work Related or Non-Work Related Observation?:</b>	Work Related
<b>Exact Location or Project of Act/Condition/Safe Behaviour:</b>	Dominion solar construction site
<b>Observation Type:</b>	Safe Behaviour
<b>Observer Name:</b>	Valeri, Stephen
<b>Observer Email Address:</b>	greg.williams@woodplc.com
<b>Stakeholder:</b>	Wood
<b>Observation Date:</b>	25-Apr-2019
<b>Observation Time:</b>	11:30
<b>Observation Close Date:</b>	25-Apr-2019
<b>Observation Category:</b>	Contractor Site safety Safety induction and briefings
<b>Name of Individual or Team:</b>	Steve Valeri
<b>Details of safety observation:</b>	project for wood-sts involved safety requirements not typical for wood eis projects, and required additional actions not known at the time of proposal to meet client requirements
<b>Immediate action taken:</b>	completed additional pre-site steps to meet client safety compliance
<b>Supporting Information:</b>	
<b>Feedback required?:</b>	No