

Observation Number:	201919504
Originator:	
Date Created:	04-Aug-2019
Business Unit:	Operations
Business Group:	Asia Pacific
Project/Office:	BSP Facilities Rejuvenation Project
Sub Business Group:	APAC Central
Site/Office Name:	BSP Facilities - Offshore
Work Related or Non-Work Related Observation?:	Work Related
Exact Location or Project of Act/Condition/Safe Behaviour:	GP spider deck
Observation Type:	Unsafe Condition
Observer Name:	Arnel Balita
Observer Email Address:	eric.roth@woodplc.com
Stakeholder:	Wood
Observation Date:	04-Aug-2019
Observation Time:	07:30
Observation Close Date:	08-Aug-2019
Observation Category:	Contractor Site safety Housekeeping
Details of safety observation:	while dismantling the scaffolding, noticed that alot of left materials on the scaffolding platform
Immediate action taken:	We secure the material and inform the person responsible.
Supporting Information:	
Feedback required?:	No