

Observation Number:	201809728
Originator:	
Date Created:	11-Jul-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Service Line:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Home or Work Related Observation?:	Work
Exact Location or Project of Act/Condition/Safe Behaviour:	Barton Street, Tewkesbury
Observation Type:	Unsafe Act
Observer Name:	Mick Bryan
Observer Email Address:	carl.jones@wwutilities.co.uk
Stakeholder:	Wood
Observation Date:	01-Feb-2018
Observation Time:	15:30
Observation Close Date:	16-Jul-2018
Details of safety observation:	The new mains clamp is not working on the 75 ml main , it does ot work it is not compatible with the 75 ml pipe . The team previously used a strap on clamp and this worked . The new only on works on 63 - 180 not 75 ml
Immediate action taken:	The team raised an Heart Observation and will return the clap to Rod Evans in the stores to pass ontoThomas James to investigaste. They will also pick up another clamp
Supporting Information:	
Feedback required?:	No