

<b>Observation Number:</b>	201905813
<b>Originator:</b>	
<b>Date Created:</b>	27-Mar-2019
<b>Business Unit:</b>	Projects
<b>Business Group:</b>	Process & Chemicals
<b>Project/Office:</b>	US & LATAM - Houston Office (for use prior to April 1)
<b>Sub Business Group:</b>	Americas
<b>Site/Office Name:</b>	US & LATAM - Houston Office
<b>Work Related or Non-Work Related Observation?:</b>	Work Related
<b>Exact Location or Project of Act/Condition/Safe Behaviour:</b>	Celanese Bishop Facility
<b>Observation Type:</b>	Unsafe Condition
<b>Observer Name:</b>	Ernest Ortega
<b>Observer Email Address:</b>	ernest.ortega_contractor@celanese.com
<b>Stakeholder:</b>	Wood
<b>Observation Date:</b>	27-Mar-2019
<b>Observation Time:</b>	14:00
<b>Observation Close Date:</b>	28-Mar-2019
<b>Observation Category:</b>	Work Environment Pedestrian routes (floors, stairs etc.)
<b>Details of safety observation:</b>	Light rain and the metal stairs and handrails were wet and slippery
<b>Immediate action taken:</b>	Took extra precaution not to slip.
<b>Supporting Information:</b>	
<b>Feedback required?:</b>	No