

Observation Number:	201925125
Originator:	
Date Created:	20-Sep-2019
Business Unit:	Projects
Business Group:	Process & Chemicals
Project/Office:	Kemerton Project
Sub Business Group:	Mining & Minerals
Site/Office Name:	Kemerton Project Site
Work Related or Non-Work Related Observation?:	Work Related
Exact Location or Project of Act/Condition/Safe Behaviour:	SMP laydown area
Observation Type:	Safe Behaviour
Observer Name:	Stephen Andrews
Observer Email Address:	steve.andrews3@woodplc.com
Stakeholder:	3rd Party
Observation Date:	20-Sep-2019
Observation Time:	14:30
Observation Close Date:	20-Sep-2019
Observation Category:	Integrity Management Competence
Name of Individual or Team:	SMS Scaffolding
Details of safety observation:	Observed scaffolder's building tank scaffold, task was done in a safe and competent manner everything in place task was discussed between all parties and grounds for erecting agreed on a practical basis .
Immediate action taken:	Observed for some time congratulated on task well done
Supporting Information:	
Feedback required?:	No