

Observation Number:	201809629
Originator:	
Date Created:	09-Jul-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Sub Business Group:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Work Related or Non-Work Related Observation?:	Work Related
Exact Location or Project of Act/Condition/Safe Behaviour:	Well spring terrace Risca
Observation Type:	Unsafe Condition
Observer Name:	Daniel Pritchard
Observer Email Address:	carl.jones@wwutilities.co.uk
Stakeholder:	Wood
Observation Date:	30-Jan-2018
Observation Time:	10:15
Observation Close Date:	16-Jul-2018
Details of safety observation:	The new mains clamp is not working on the 75 ml main , it does ot work it is not compatible with the 75 ml pipe . The team previously used a strap on clamp and this worked . The new only on works on 63 - 180 not 75 ml
Immediate action taken:	The team raised an Heart Observation and will return the clap to Rod Evans in the stores to pass ontoThomas James to investigaste. They will also pick up another clamp
Supporting Information:	
Feedback required?:	No