

Observation Number:	201810255
Originator:	
Date Created:	18-Jul-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Sub Business Group:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Work Related or Non-Work Related Observation?:	Work Related
Exact Location or Project of Act/Condition/Safe Behaviour:	Strongbow Road, Chepstow
Observation Type:	Unsafe Act
Observer Name:	Matthew Rees
Observer Email Address:	carl.jones@wwutilities.co.uk
Stakeholder:	Wood
Observation Date:	16-Mar-2018
Observation Time:	14:30
Observation Close Date:	18-Jul-2018
Details of safety observation:	Vac Ex driver onsite doesn't have correct paperwork - REF46
Immediate action taken:	Matt stopped them from working - gave them a Ref 46 document to complete, to allow him to carry on working. Matt asked if he had any Ref 46 documents and John said he didn't have any.
Supporting Information:	
Feedback required?:	No