

Observation Number:	201809735
Originator:	
Date Created:	11-Jul-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Sub Business Group:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Work Related or Non-Work Related Observation?:	Work Related
Exact Location or Project of Act/Condition/Safe Behaviour:	River Terrace Porth RTC
Observation Type:	Unsafe Condition
Observer Name:	Dai Bailey
Observer Email Address:	trevor.clark@wwutilities.co.uk
Stakeholder:	Wood
Observation Date:	02-Feb-2018
Observation Time:	08:00
Observation Close Date:	
Details of safety observation:	Intervention :Barriers down due to bad weather conditions
Immediate action taken:	Barriers were picked back up taped /secured
Supporting Information:	
Feedback required?:	No
Comments from Reviewer	
Cancel Comments:	Not Wood related