

<b>Observation Number:</b>	201605267
<b>Originator:</b>	
<b>Date Created:</b>	10-Aug-2016
<b>Business Unit:</b>	AS EAAA
<b>Business Group:</b>	Capital Projects EAAA
<b>Project/Office:</b>	EPC2 Antwerp
<b>Service Line:</b>	SERC
<b>Site/Office Name:</b>	EPC2 Antwerp - Site
<b>Home or Work Related Observation?:</b>	Work
<b>Exact Location or Project of Act/Condition/Safe Behaviour:</b>	J-101 near 2-TF-6 area
<b>Observation Type:</b>	Safe Behaviour
<b>Observer Name:</b>	Cristian Loi
<b>Observer Email Address:</b>	TIOTIE.ExxonmobilAntwerp@fwceu.com
<b>Stakeholder:</b>	Contractor
<b>Observation Date:</b>	09-Aug-2016
<b>Observation Time:</b>	08:30
<b>Observation Close Date:</b>	12-Aug-2016
<b>Name of Individual or Team:</b>	TECHIMP
<b>Details of safety observation:</b>	TECHIMP crew were busy with the relocation of a power socket inside the J-101 in order to proceed with the relocation of an flex station. Since the power socket was under voltage, as per the work permit, before to start the activities it was necessary to perform the LOTO procedure with EM. The procedure was followed correctly and so they started to work in a safe way.
<b>Immediate action taken:</b>	No action but congratulations.
<b>Supporting Information:</b>	
<b>Feedback required?:</b>	No