

Originator:	
Date Created:	24-Jun-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Service Line:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Home or Work Related Observation?:	Work
Exact Location or Project of Act/Condition/Safe Behaviour:	Willows at Stone House, Stroud
Observation Type:	Unsafe Condition
Observer Name:	Micky Wright
Observer Email Address:	trevor.clark@wwutilities.co.uk
Stakeholder:	Wood
Observation Date:	12-Jan-2018
Observation Time:	11:30
Observation Close Date:	27-Jun-2018
Details of safety observation:	Gas valve (new box) fitted? Reinstatement up on site and found carriage way job, no signs out for the job, a plate in road with no signs and no barriers.
Immediate action taken:	Reinstatement team reported this on the Heart Observation line , put men at work signs out and directional signs out to make site safe and secure. Mark Green has spoken to the team and told them to make sure the site is left safe and secure like that have already put in place
Supporting Information:	
Feedback required?:	No