

Originator:	
Date Created:	03-Jul-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Service Line:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Home or Work Related Observation?:	Work
Exact Location or Project of Act/Condition/Safe Behaviour:	Ridge rd Torquay
Observation Type:	Unsafe Act
Observer Name:	Chris Wilde
Observer Email Address:	john.dowson@wwutilities.co.uk
Stakeholder:	Wood
Observation Date:	29-Jan-2018
Observation Time:	12:30
Observation Close Date:	
Details of safety observation:	Chris Wilde attended site to do Cat / Genny down load the. T/L already marked the position of the HV cable but the Cat / Genny assessment showed the markings were incorrect . The T/L was aware that he could not carry out until he passed his assessment
Immediate action taken:	T/L failed , he was given a TBT before he could carry out on site
Supporting Information:	
Feedback required?:	No
Comments from Reviewer	
Cancel Comments:	Not wood related