

Observation Number:	201809731
Originator:	
Date Created:	11-Jul-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Service Line:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Work Related or Non-Work Related Observation?:	Work Related
Exact Location or Project of Act/Condition/Safe Behaviour:	llantwit road, pontypridd
Observation Type:	Unsafe Condition
Observer Name:	Mark Bees
Observer Email Address:	trevor.clark@wwutilities.co.uk
Stakeholder:	Contractor
Observation Date:	01-Feb-2018
Observation Time:	13:45
Observation Close Date:	
Details of safety observation:	ISL: team audit, fire extinguisher out of calibration end of january 2018
Immediate action taken:	Mark bees exchanged unit on return to yard 01.2.18.there was 2 other untis available if required.
Supporting Information:	
Feedback required?:	No
Comments from Reviewer	
Cancel Comments:	Not Wood related