

Observation Number:	201904156	
Originator:		
Date Created:	12-Mar-2019	
Business Unit:	Projects	
Business Group:	Conventional Energy	
Project/Office:	South Africa Home Office	
Sub Business Group:	Europe & Africa	
Site/Office Name:	Midrand Office	
Work Related or Non-Work Related Observation?:	Work Related	
Exact Location or Project of Act/Condition/Safe Behaviour:	The smoking area located by block A under thatch roof area.	
Observation Type:	Unsafe Condition	
Observer Name:	Rene	
Observer Email Address:	rene.bosman@woodplc.com	
Stakeholder:	Wood	
Observation Date:	12-Mar-2019	
Observation Time:	11:00	
Observation Close Date:	18-Mar-2019	
Observation Category:	Work Environment Furniture and Work equipment	
Details of safety observation:	The cement table top is off centered and may fall to the one side.	
Immediate action taken:	Observer called maintenance to investigate and move the table top back to the center.	
Supporting Information:		
Feedback required?:	No	
Reasons for Amendment		
Comment	Entered By	Date Entered
Observation has been closed out and hazard has been satisfactorily addressed	Daniel Roodt	18-March-2019 09:41