

<b>Observation Number:</b>	201919504
<b>Originator:</b>	
<b>Date Created:</b>	04-Aug-2019
<b>Business Unit:</b>	Operations
<b>Business Group:</b>	Asia Pacific
<b>Project/Office:</b>	BSP Facilities Rejuvenation Project
<b>Sub Business Group:</b>	APAC Central
<b>Site/Office Name:</b>	BSP Facilities - Offshore
<b>Work Related or Non-Work Related Observation?:</b>	Work Related
<b>Exact Location or Project of Act/Condition/Safe Behaviour:</b>	GP spider deck
<b>Observation Type:</b>	Unsafe Condition
<b>Observer Name:</b>	Arnel Balita
<b>Observer Email Address:</b>	eric.roth@woodplc.com
<b>Stakeholder:</b>	Wood
<b>Observation Date:</b>	04-Aug-2019
<b>Observation Time:</b>	07:30
<b>Observation Close Date:</b>	08-Aug-2019
<b>Observation Category:</b>	Contractor Site safety Housekeeping
<b>Details of safety observation:</b>	while dismantling the scaffolding, noticed that alot of left materials on the scaffolding platform
<b>Immediate action taken:</b>	We secure the material and inform the person responsible.
<b>Supporting Information:</b>	
<b>Feedback required?:</b>	No