

Originator:	
Date Created:	18-Jul-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Service Line:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Home or Work Related Observation?:	Work
Exact Location or Project of Act/Condition/Safe Behaviour:	Ystrad Deri Tredegar
Observation Type:	Unsafe Condition
Observer Name:	Richard Date
Observer Email Address:	carl.jones@wwutilities.co.uk
Stakeholder:	Wood
Observation Date:	29-May-2018
Observation Time:	08:00
Observation Close Date:	12-Sep-2018
Details of safety observation:	Team arrived on site this morning and all black tape on the barriers had been cut, leaving the walk way open that had been previously closed and signed open . All signs had been thrown everywhere
Immediate action taken:	The team re- signed the site and barriered off the walkway to close again . Leaving the site safe and secure
Supporting Information:	
Feedback required?:	No