

<b>Originator:</b>	
<b>Date Created:</b>	12-Mar-2019
<b>Business Unit:</b>	AS EAAA
<b>Business Group:</b>	Capital Projects EAAA
<b>Project/Office:</b>	South Africa Home Office
<b>Service Line:</b>	NEMEA
<b>Site/Office Name:</b>	Midrand Office
<b>Home or Work Related Observation?:</b>	Work
<b>Exact Location or Project of Act/Condition/Safe Behaviour:</b>	The smoking area located by block A under thatch roof area.
<b>Observation Type:</b>	Unsafe Condition
<b>Observer Name:</b>	Rene
<b>Observer Email Address:</b>	rene.bosman@woodplc.com
<b>Stakeholder:</b>	Wood
<b>Observation Date:</b>	12-Mar-2019
<b>Observation Time:</b>	11:00
<b>Observation Close Date:</b>	18-Mar-2019
<b>Observation Category:</b>	Work Environment Furniture and Work equipment
<b>Details of safety observation:</b>	The cement table top is off centered and may fall to the one side.
<b>Immediate action taken:</b>	Observer called maintenance to investigate and move the table top back to the center.
<b>Supporting Information:</b>	
<b>Feedback required?:</b>	No
<b>Reasons for Amendment</b>	
<b>Comment</b>	<b>Entered By    Date Entered</b>
Observation has been closed out and hazard has been satisfactorily addressed	Daniel Roodt    18-March-2019 09:41