

| | |
|---|--|
| Observation Number: | 201925537 |
| Originator: | |
| Date Created: | 26-Sep-2019 |
| Business Unit: | Projects |
| Business Group: | Process & Chemicals |
| Project/Office: | Kemerton Project |
| Sub Business Group: | Mining & Minerals |
| Site/Office Name: | Kemerton Project Site |
| Work Related or Non-Work Related Observation?: | Work Related |
| Exact Location or Project of Act/Condition/Safe Behaviour: | Train One Hydromet Area |
| Observation Type: | Safe Behaviour |
| Observer Name: | Stephen Andrews |
| Observer Email Address: | steve.andrews3@woodplc.com |
| Stakeholder: | Wood |
| Observation Date: | 26-Sep-2019 |
| Observation Time: | 08:30 |
| Observation Close Date: | 26-Sep-2019 |
| Observation Category: | Work Environment Pedestrian routes (floors, stairs etc.) |
| Name of Individual or Team: | Civmec |
| Details of safety observation: | Lifting in pre-cast concrete sumps, hole in sump which pedestrians have the potential to fall were covered to protect from falling in prior to installation. |
| Immediate action taken: | Good initiative by contractor to identify the potential hazard and take steps to mitigate hazard |
| Supporting Information: | |
| Feedback required?: | No |