

Originator:	
Date Created:	16-Jul-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Service Line:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Home or Work Related Observation?:	Work
Exact Location or Project of Act/Condition/Safe Behaviour:	Merafield Drive Plymton
Observation Type:	Unsafe Condition
Observer Name:	Matt Raasch-sotinwa
Observer Email Address:	chris.wilde@amecfw.com
Stakeholder:	Wood
Observation Date:	07-Feb-2018
Observation Time:	08:45
Observation Close Date:	
Details of safety observation:	Team about to start work and they had x1 fire extinguisher and x1 BA .
Immediate action taken:	The team were asked where the other fire extinguisher was it was in the van not charged up (T/L was reluctant to get the second fire extinguisher out of the van)
Supporting Information:	
Feedback required?:	No
Comments from Reviewer	
Cancel Comments:	Not Wood related