

Observation Number:	201809623
Originator:	
Date Created:	09-Jul-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Sub Business Group:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Work Related or Non-Work Related Observation?:	Work Related
Exact Location or Project of Act/Condition/Safe Behaviour:	Apperley Glous
Observation Type:	Unsafe Condition
Observer Name:	Mickey Wright
Observer Email Address:	trevor.clark@wwutilities.co.uk
Stakeholder:	Contractor
Observation Date:	28-Jan-2018
Observation Time:	10:15
Observation Close Date:	
Details of safety observation:	Complete Utilities: The balance wheel off the roller has sheared of the axcel
Immediate action taken:	This has now been replaced this morning
Supporting Information:	
Feedback required?:	No
Comments from Reviewer	
Cancel Comments:	Not Wood related