

|   |  |
|---|--|
| <b>Observation Number:</b>  | 201806662  |
| <b>Originator:</b>  |  |
| <b>Date Created:</b>  | 19-May-2018  |
| <b>Business Unit:</b>   | E&I Solutions  |
| <b>Business Group:</b>  | Western US   |
| <b>Project/Office:</b>  | United States - West   |
| <b>Site/Office Name:</b>  | Seattle, WA  |
| <b>Work Related or Non-Work Related Observation?:</b>             | Work Related   |
| <b>Exact Location or Project of Act/Condition/Safe Behaviour:</b> | West Lime Silo Culvert Excavation - Bunker Hill Central Treatment Plant.   |
| <b>Observation Type:</b>  | Safe Behaviour   |
| <b>Observer Name:</b>   | Khalfani Lee   |
| <b>Observer Email Address:</b>                                    | khalfani.lee@woodplc.com   |
| <b>Stakeholder:</b>   | Wood   |
| <b>Observation Date:</b>  | 14-May-2018  |
| <b>Observation Time:</b>  | 10:00  |
| <b>Observation Close Date:</b>                                    | 21-May-2018  |
| <b>Name of Individual or Team:</b>                                | Northwind  |
| <b>Details of safety observation:</b>                             | The Northwind team noticed that ground water was threatening their excavation and did a safety stand down to get the onsite SSHO and reassess their work plan. |
| <b>Immediate action taken:</b>                                    | A dewatering plan and effort was implemented which kept the worksite safe and assisted in maintaining QC compliance as well during compaction efforts.         |
| <b>Supporting Information:</b>                                    |  |
| <b>Feedback required?:</b>  | No   |