

<b>Observation Number:</b>	201808418
<b>Originator:</b>	
<b>Date Created:</b>	24-Jun-2018
<b>Business Unit:</b>	AS EAAA
<b>Business Group:</b>	Operations Services Europe & Africa
<b>Project/Office:</b>	Western Gas Alliance
<b>Service Line:</b>	Transmission & Distribution
<b>Site/Office Name:</b>	Western Gas Alliance 1855005/6
<b>Home or Work Related Observation?:</b>	Work
<b>Exact Location or Project of Act/Condition/Safe Behaviour:</b>	East Wales
<b>Observation Type:</b>	Unsafe Condition
<b>Observer Name:</b>	Richard Date
<b>Observer Email Address:</b>	carl.joes@wwutilities.co.uk
<b>Stakeholder:</b>	Wood
<b>Observation Date:</b>	08-Jan-2018
<b>Observation Time:</b>	08:30
<b>Observation Close Date:</b>	27-Jun-2018
<b>Details of safety observation:</b>	Friday 5th Jan before the team left site the excavation in the rd out number 2 had heras fencing over the excavation all barriered off/ taped safe and secure all signs up for customers to see . Came in this morning and the barriers had been removed from the excavation leaving it open and signs and heras fencing had been removed and thrown everywhere. A customer in number16 came out and told the Team Leader that over the weekend a vehicle hit an arrow sign that had been thrown and she was just informing the T/L incase we have a phone call
<b>Immediate action taken:</b>	Team Leader reported on the heart observation log to keep us updated and just in case we have a phone call regarding this . Team tided up the site and made it safe and secure
<b>Supporting Information:</b>	
<b>Feedback required?:</b>	No