

<b>Observation Number:</b>	201810602
<b>Originator:</b>	
<b>Date Created:</b>	24-Jul-2018
<b>Business Unit:</b>	AS EAAA
<b>Business Group:</b>	Operations Services Europe & Africa
<b>Project/Office:</b>	Western Gas Alliance
<b>Service Line:</b>	Transmission & Distribution
<b>Site/Office Name:</b>	Western Gas Alliance 1855005/6
<b>Home or Work Related Observation?:</b>	Work
<b>Exact Location or Project of Act/Condition/Safe Behaviour:</b>	The rear of Rhondda Terrace Ferndale
<b>Observation Type:</b>	Unsafe Condition
<b>Observer Name:</b>	Peter Tyler
<b>Observer Email Address:</b>	carl.jones@wwutilities.co.uk
<b>Stakeholder:</b>	Wood
<b>Observation Date:</b>	16-Jul-2018
<b>Observation Time:</b>	08:15
<b>Observation Close Date:</b>	21-Sep-2018
<b>Details of safety observation:</b>	Welfare unit on site WGAP 13119, has not been cleaned for 3 weeks
<b>Immediate action taken:</b>	Contacted A1 Loo hire they will be cleaning the Welfare Unit Tomorrow. Cleaned ref Peter Tyler 19/07/2018
<b>Supporting Information:</b>	
<b>Feedback required?:</b>	No