

<b>Observation Number:</b>	201911812
<b>Originator:</b>	
<b>Date Created:</b>	30-May-2019
<b>Business Unit:</b>	Projects
<b>Business Group:</b>	Process & Chemicals
<b>Project/Office:</b>	Kemerton Project
<b>Sub Business Group:</b>	Mining & Minerals
<b>Site/Office Name:</b>	Kemerton Project Site
<b>Work Related or Non-Work Related Observation?:</b>	Work Related
<b>Exact Location or Project of Act/Condition/Safe Behaviour:</b>	kemerton Site lot 7 & 8 stage 2
<b>Observation Type:</b>	Safe Behaviour
<b>Observer Name:</b>	Stephen Andrews
<b>Observer Email Address:</b>	steve.andrews3@woodplc.com
<b>Stakeholder:</b>	Contractor
<b>Observation Date:</b>	30-May-2019
<b>Observation Time:</b>	09:15
<b>Observation Close Date:</b>	30-May-2019
<b>Observation Category:</b>	Contractor Site safety Safety planning
<b>Name of Individual or Team:</b>	Kyle C & S drainage
<b>Details of safety observation:</b>	Observed Kyle from C & S drainage installing sub soil drainage on the above lots , JHA in place and covered all aspects of task, barricading & winn rows established , good house keeping and access egress to trenching
<b>Immediate action taken:</b>	Pat on the back for doing a good job.
<b>Supporting Information:</b>	
<b>Feedback required?:</b>	No