

Observation Number:	201808426
Originator:	
Date Created:	24-Jun-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Service Line:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Home or Work Related Observation?:	Work
Exact Location or Project of Act/Condition/Safe Behaviour:	3 Bryn Milwr Cwmbran
Observation Type:	Unsafe Condition
Observer Name:	Gareth Gullidge
Observer Email Address:	carl.jones@wwutilities.co.uk
Stakeholder:	Wood
Observation Date:	17-Jan-2018
Observation Time:	09:30
Observation Close Date:	27-Jun-2018
Details of safety observation:	Team have come across asbestos on site
Immediate action taken:	Team have stopped work contacted FLM who will be coming to site with the appropriate asbestos bagging : correct PPE worn,Dust Masks, White overalls, Double gloves etc. . To disposed of correctly. Ref 95 issued and permit to work issued by Sean Maher
Supporting Information:	
Feedback required?:	No