

|   |   |
|---|---|
| <b>Observation Number:</b>  | 201809736   |
| <b>Originator:</b>  |   |
| <b>Date Created:</b>  | 11-Jul-2018   |
| <b>Business Unit:</b>   | AS EAAA   |
| <b>Business Group:</b>  | Operations Services Europe & Africa   |
| <b>Project/Office:</b>  | Western Gas Alliance  |
| <b>Sub Business Group:</b>  | Transmission & Distribution   |
| <b>Site/Office Name:</b>  | Western Gas Alliance 1855005/6  |
| <b>Work Related or Non-Work Related Observation?:</b>             | Work Related  |
| <b>Exact Location or Project of Act/Condition/Safe Behaviour:</b> | Gardeners way Kings Stanley   |
| <b>Observation Type:</b>  | Unsafe Condition  |
| <b>Observer Name:</b>   | Micky Wright  |
| <b>Observer Email Address:</b>                                    | trevor.clark@wwutilities.co.uk  |
| <b>Stakeholder:</b>   | Contractor  |
| <b>Observation Date:</b>  | 05-Feb-2018   |
| <b>Observation Time:</b>  | 10:00   |
| <b>Observation Close Date:</b>                                    |   |
| <b>Details of safety observation:</b>                             | Complete Utilities:Road plates left in road causing trip hazard when footway is closed. |
| <b>Immediate action taken:</b>                                    | The team have removed boards and stacked safely. Job No 6/395696                        |
| <b>Supporting Information:</b>                                    |   |
| <b>Feedback required?:</b>  | No  |
| <b>Comments from Reviewer</b>                                     |   |
| <b>Cancel Comments:</b>   | Not Wood related  |