

|   |   |
|---|---|
| <b>Observation Number:</b>  | 201808423   |
| <b>Originator:</b>  |   |
| <b>Date Created:</b>  | 24-Jun-2018   |
| <b>Business Unit:</b>   | AS EAAA   |
| <b>Business Group:</b>  | Operations Services Europe & Africa   |
| <b>Project/Office:</b>  | Western Gas Alliance  |
| <b>Service Line:</b>  | Transmission & Distribution   |
| <b>Site/Office Name:</b>  | Western Gas Alliance 1855005/6  |
| <b>Home or Work Related Observation?:</b>                         | Work  |
| <b>Exact Location or Project of Act/Condition/Safe Behaviour:</b> | Chestnut Way, Gurnos  |
| <b>Observation Type:</b>  | Unsafe Condition  |
| <b>Observer Name:</b>   | Richard Date  |
| <b>Observer Email Address:</b>                                    | carl.joes@wwutilities.co.uk   |
| <b>Stakeholder:</b>   | Wood  |
| <b>Observation Date:</b>  | 12-Jan-2018   |
| <b>Observation Time:</b>  | 08:30   |
| <b>Observation Close Date:</b>                                    | 27-Jun-2018   |
| <b>Details of safety observation:</b>                             | Heavy rain, high winds, barriers everywhere, and they were sandbagged and taped and weighted before team left on Friday |
| <b>Immediate action taken:</b>                                    | Team have made site safe and secure, and reported Monday morning.   |
| <b>Supporting Information:</b>                                    |   |
| <b>Feedback required?:</b>  | No  |