

|   |   |
|---|---|
| <b>Observation Number:</b>  | 201810599   |
| <b>Originator:</b>  |   |
| <b>Date Created:</b>  | 24-Jul-2018   |
| <b>Business Unit:</b>   | AS EAAA   |
| <b>Business Group:</b>  | Operations Services Europe & Africa   |
| <b>Project/Office:</b>  | Western Gas Alliance  |
| <b>Service Line:</b>  | Transmission & Distribution   |
| <b>Site/Office Name:</b>  | Western Gas Alliance 1855005/6  |
| <b>Home or Work Related Observation?:</b>                         | Work  |
| <b>Exact Location or Project of Act/Condition/Safe Behaviour:</b> | Old St Clears Carmathen   |
| <b>Observation Type:</b>  | Unsafe Condition  |
| <b>Observer Name:</b>   | John Hulse  |
| <b>Observer Email Address:</b>                                    | steve.edwards@wwutilities.co.uk   |
| <b>Stakeholder:</b>   | Wood  |
| <b>Observation Date:</b>  | 06-Jul-2018   |
| <b>Observation Time:</b>  | 10:15   |
| <b>Observation Close Date:</b>                                    | 12-Sep-2018   |
| <b>Details of safety observation:</b>                             | Hypodermic needles found on site on our works in the grass verge                                |
| <b>Immediate action taken:</b>                                    | FLM contacted the council and they came out cleared the hypodermic needles and disposed of them |
| <b>Supporting Information:</b>                                    |   |
| <b>Feedback required?:</b>  | No  |