

Observation Number:	201806662
Originator:	
Date Created:	19-May-2018
Business Unit:	E&I Solutions
Business Group:	Western US
Project/Office:	United States - West
Site/Office Name:	Seattle, WA
Home or Work Related Observation?:	Work
Exact Location or Project of Act/Condition/Safe Behaviour:	West Lime Silo Culvert Excavation - Bunker Hill Central Treatment Plant.
Observation Type:	Safe Behaviour
Observer Name:	Khalfani Lee
Observer Email Address:	khalfani.lee@woodplc.com
Stakeholder:	Wood
Observation Date:	14-May-2018
Observation Time:	10:00
Observation Close Date:	21-May-2018
Name of Individual or Team:	Northwind
Details of safety observation:	The Northwind team noticed that ground water was threatening their excavation and did a safety stand down to get the onsite SSHO and reassess their work plan.
Immediate action taken:	A dewatering plan and effort was implemented which kept the worksite safe and assisted in maintaining QC compliance as well during compaction efforts.
Supporting Information:	
Feedback required?:	No