

Observation Number:	201809248
Originator:	
Date Created:	03-Jul-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Sub Business Group:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Work Related or Non-Work Related Observation?:	Work Related
Exact Location or Project of Act/Condition/Safe Behaviour:	36 Wern Isaf Merthyr Tydfil
Observation Type:	Unsafe Condition
Observer Name:	Ian Palmer
Observer Email Address:	carl.jones@wwutilities.co.uk
Stakeholder:	Wood
Observation Date:	10-Jan-2018
Observation Time:	11:00
Observation Close Date:	16-Jul-2018
Details of safety observation:	When tried to fuse this top tee it did not fuse, so cut the 32-20 reducer off
Immediate action taken:	T/L gave it to Tommy Richards to send back for investigation.
Supporting Information:	
Feedback required?:	No