

Observation Number:	201903160
Originator:	
Date Created:	26-Feb-2019
Business Unit:	E&I Solutions
Business Group:	Canada
Project/Office:	Canada - West
Site/Office Name:	Edmonton, AB
Home or Work Related Observation?:	Work
Exact Location or Project of Act/Condition/Safe Behaviour:	One step off the carpet from the main floor back entrance
Observation Type:	Unsafe Condition
Observer Name:	Natalie Tremblay
Observer Email Address:	natalie.tremblay@woodplc.com
Stakeholder:	Wood
Observation Date:	11-Feb-2019
Observation Time:	10:30
Observation Close Date:	26-Feb-2019
Observation Category:	Work Environment Pedestrian routes (floors, stairs etc.)
Details of safety observation:	I stepped off the mat onto the polished concrete and slipped. I caught myself before I fell but was not impressed with the lack of carpet/polished floor.
Immediate action taken:	Told Tim Kihn
Supporting Information:	
Feedback required?:	No