

| | |
|---|---|
| Observation Number: | 201901097 |
| Originator: | |
| Date Created: | 28-Jan-2019 |
| Business Unit: | AS EAAA |
| Business Group: | Capital Projects EAAA |
| Project/Office: | Chennai Home Office |
| Service Line: | India |
| Site/Office Name: | Chennai Home Office |
| Work Related or Non-Work Related Observation?: | Work Related |
| Exact Location or Project of Act/Condition/Safe Behaviour: | Internal road leading to Exit no 2. |
| Observation Type: | Unsafe Act |
| Observer Name: | Kumar, Anil |
| Observer Email Address: | anil.kumar@woodplc.com |
| Stakeholder: | Wood |
| Observation Date: | 25-Jan-2019 |
| Observation Time: | 17:30 |
| Observation Close Date: | 07-Aug-2019 |
| Observation Category: | Work Environment Pedestrian routes (floors, stairs etc.) |
| Details of safety observation: | A lot of jay walkers in small groups walk along the roads occupying almost half of the drive way. They all appear to be from the same company and seen every day. They are seen walking along the left side of the road in the same direction of the evening traffic and sometimes cross the road abruptly. The issue is compounded by the several cabs parked on either side of the road. This may potentially cause accidents. In the past jay walkers were discouraged by security guards.; not seen anymore. May be taken up with the building authorities. Thanks. |
| Immediate action taken: | None. |
| Supporting Information: | |
| Feedback required?: | No |
| Comments from Reviewer | |
| Action to be taken: | Action taken: Signage's have been placed by Building management. |
| Supporting Information: | |
| Comments from OU Admin | |
| Closing Comments: | Action Completed. |