

<b>Observation Number:</b>	201913505
<b>Originator:</b>	
<b>Date Created:</b>	19-Jun-2019
<b>Business Unit:</b>	Projects
<b>Business Group:</b>	Process & Chemicals
<b>Project/Office:</b>	Kemerton Project
<b>Sub Business Group:</b>	Mining & Minerals
<b>Site/Office Name:</b>	Kemerton Project Site
<b>Work Related or Non-Work Related Observation?:</b>	Work Related
<b>Exact Location or Project of Act/Condition/Safe Behaviour:</b>	Main common trench HV Sub
<b>Observation Type:</b>	Safe Behaviour
<b>Observer Name:</b>	Stephen Andrews
<b>Observer Email Address:</b>	steve.andrews3@woodplc.com
<b>Stakeholder:</b>	Contractor
<b>Observation Date:</b>	19-Jun-2019
<b>Observation Time:</b>	13:30
<b>Observation Close Date:</b>	19-Jun-2019
<b>Observation Category:</b>	Contractor Site safety Procedure implementation
<b>Name of Individual or Team:</b>	Nilsen eletrical
<b>Details of safety observation:</b>	Observed Nilsen Electrical setting up to winch cables from drum through excavated trench 500meters, set up was supervised by BGC all procedures and barricades were in place and tagged with relevant information, communication between winch operator and drum operator were clear and understandable time was taken in the execution of task to ensure every thing was covered.
<b>Immediate action taken:</b>	Congratulated team on job well done and encouraged them to keep up the good skills they had introduced .
<b>Supporting Information:</b>	
<b>Feedback required?:</b>	No