

Observation Number:	201808477
Originator:	
Date Created:	25-Jun-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Service Line:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Home or Work Related Observation?:	Work
Exact Location or Project of Act/Condition/Safe Behaviour:	30 Northfield way Swindon
Observation Type:	Unsafe Condition
Observer Name:	Andy Lock
Observer Email Address:	trevor.clark@wwutilities.co.uk
Stakeholder:	Wood
Observation Date:	25-Jan-2018
Observation Time:	08:15
Observation Close Date:	27-Jun-2018
Details of safety observation:	Complete Utilities:Team arrived on site this morning and found all barriers/signs were down not sure if it was due to the adverse weather conditions or other vehicles
Immediate action taken:	The team picked up all barriers / signs and made the site safe and secure
Supporting Information:	
Feedback required?:	No