

Observation Number:	201808468
Originator:	
Date Created:	25-Jun-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Service Line:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Home or Work Related Observation?:	Work
Exact Location or Project of Act/Condition/Safe Behaviour:	North Rocks Rd Swansea
Observation Type:	Unsafe Condition
Observer Name:	Kevin Howard
Observer Email Address:	john.howson@wwutilities.co.uk
Stakeholder:	Wood
Observation Date:	19-Jan-2018
Observation Time:	11:15
Observation Close Date:	27-Jun-2018
Details of safety observation:	The team were excavating with the machine in a footpath without No electric mark ups and No cat on site
Immediate action taken:	Kevin stopped the job completely and told the team to pack up and leave the site safe and secure for the weekend
Supporting Information:	
Feedback required?:	No