

<b>Observation Number:</b>	201927117
<b>Originator:</b>	
<b>Date Created:</b>	10-Oct-2019
<b>Business Unit:</b>	Projects
<b>Business Group:</b>	Process & Chemicals
<b>Project/Office:</b>	Kemerton Project
<b>Sub Business Group:</b>	Mining & Minerals
<b>Site/Office Name:</b>	Kemerton Project Site
<b>Work Related or Non-Work Related Observation?:</b>	Work Related
<b>Exact Location or Project of Act/Condition/Safe Behaviour:</b>	Lifting of tank sections into position SMP assembly area
<b>Observation Type:</b>	Safe Behaviour
<b>Observer Name:</b>	Stephen Andrews
<b>Observer Email Address:</b>	steve.andrews3@woodplc.com
<b>Stakeholder:</b>	Contractor
<b>Observation Date:</b>	10-Oct-2019
<b>Observation Time:</b>	08:15
<b>Observation Close Date:</b>	10-Oct-2019
<b>Observation Category:</b>	Contractor Site safety Safety planning
<b>Name of Individual or Team:</b>	Civmec SMP team
<b>Details of safety observation:</b>	Observed group lifting two tank section onto one tank section to complete fit up and weld, Checked lift stud, JHA & confined space all was correct and in place, group had team talk prior to lift so all channels of communications followed area totally barricaded from other work groups so no interface issues .
<b>Immediate action taken:</b>	Congratulated team on task well done.
<b>Supporting Information:</b>	
<b>Feedback required?:</b>	No