

<b>Observation Number:</b>	201900370
<b>Originator:</b>	
<b>Date Created:</b>	10-Jan-2019
<b>Business Unit:</b>	Consulting
<b>Business Group:</b>	Energy Optimisation & Innovation
<b>Project/Office:</b>	E&I Sustainable Infrastructure
<b>Sub Business Group:</b>	EMEA
<b>Site/Office Name:</b>	E&I Sustainable Infrastructure
<b>Work Related or Non-Work Related Observation?:</b>	Work Related
<b>Exact Location or Project of Act/Condition/Safe Behaviour:</b>	Alderbury NGGT Site: Bottom of track off bridleway to site
<b>Observation Type:</b>	Unsafe Condition
<b>Observer Name:</b>	Lewis Miffling
<b>Observer Email Address:</b>	lewis.miffling@woodplc.com
<b>Stakeholder:</b>	3rd Party
<b>Observation Date:</b>	10-Jan-2019
<b>Observation Time:</b>	12:00
<b>Observation Close Date:</b>	11-Jan-2019
<b>Observation Category:</b>	Contractor Site safety Housekeeping
<b>Details of safety observation:</b>	Landowner complained about siting of skip for waste soil arisings which is 'scaring' horses on the bridleway
<b>Immediate action taken:</b>	Gap between skip and nearest obstruction measured to check clearance. Contacted contractor to arrange skip removal
<b>Supporting Information:</b>	
<b>Feedback required?:</b>	No