

Observation Number:	201809241
Originator:	
Date Created:	03-Jul-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Service Line:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Home or Work Related Observation?:	Work
Exact Location or Project of Act/Condition/Safe Behaviour:	St Kingmark Avenue, Chepstow
Observation Type:	Unsafe Act
Observer Name:	Gary Hathway
Observer Email Address:	trevor.clark@wwutilities.co.uk
Stakeholder:	Wood
Observation Date:	26-Jan-2018
Observation Time:	10:30
Observation Close Date:	16-Jul-2018
Details of safety observation:	Intervention : turned up onsite to lay paving slabs, excavation back filled too high.
Immediate action taken:	Team have to re - dig out and carry through private garage
Supporting Information:	
Feedback required?:	No