

Observation Number:	201808471
Originator:	
Date Created:	25-Jun-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Sub Business Group:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Work Related or Non-Work Related Observation?:	Work Related
Exact Location or Project of Act/Condition/Safe Behaviour:	Meas Mor Yard Glos
Observation Type:	Unsafe Condition
Observer Name:	Mickey Wright
Observer Email Address:	trevor.clark@wwutilities.co.uk
Stakeholder:	Wood
Observation Date:	12-Jan-2018
Observation Time:	13:15
Observation Close Date:	27-Jun-2018
Details of safety observation:	Complete Utilities :Foot wacker leaking petrol
Immediate action taken:	Excahanged the footwacker and sent the other one to be repaired
Supporting Information:	
Feedback required?:	No