

<b>Observation Number:</b>	201602572
<b>Originator:</b>	
<b>Date Created:</b>	25-May-2016
<b>Business Unit:</b>	AS EAAA
<b>Business Group:</b>	Capital Projects EAAA
<b>Project/Office:</b>	EPC2 Antwerp
<b>Service Line:</b>	SERC
<b>Site/Office Name:</b>	EPC2 Antwerp - Site
<b>Home or Work Related Observation?:</b>	Work
<b>Exact Location or Project of Act/Condition/Safe Behaviour:</b>	Exxon Antwerp Refinery - PC Area - 1A Straat
<b>Observation Type:</b>	Safe Behaviour
<b>Observer Name:</b>	Cristian Loi
<b>Observer Email Address:</b>	TIOTIE.ExxonmobilAntwerp@fwceu.com
<b>Stakeholder:</b>	Contractor
<b>Observation Date:</b>	23-May-2016
<b>Observation Time:</b>	10:00
<b>Observation Close Date:</b>	30-May-2016
<b>Name of Individual or Team:</b>	Altrad
<b>Details of safety observation:</b>	ALTRAD I focused my attention to the erection of a scaffolding in 1A straat. During my observation I've seen a good use of PPE and good safety behavior regarding work at heights.
<b>Immediate action taken:</b>	No action, just compliments to the crew.
<b>Supporting Information:</b>	
<b>Feedback required?:</b>	No