

| | |
|-------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Observation Number: | 201810048 |
| Originator: | |
| Date Created: | 16-Jul-2018 |
| Business Unit: | AS EAAA |
| Business Group: | Operations Services Europe & Africa |
| Project/Office: | Western Gas Alliance |
| Service Line: | Transmission & Distribution |
| Site/Office Name: | Western Gas Alliance 1855005/6 |
| Home or Work Related Observation?: | Work |
| Exact Location or Project of Act/Condition/Safe Behaviour: | Tarris Av Kingsteignton |
| Observation Type: | Unsafe Condition |
| Observer Name: | Jason Miller |
| Observer Email Address: | john.dowson@wwutilities.co.uk |
| Stakeholder: | Wood |
| Observation Date: | 09-Feb-2018 |
| Observation Time: | 11:00 |
| Observation Close Date: | |
| Details of safety observation: | Team have staterted to do an RO , Jason Miller is the AE he turned up on site to do a audit and found Electrical Equipment OOD : Conti Board , Extension Leads ,Water Pump |
| Immediate action taken: | There is a second team so the team will be using their equipment |
| Supporting Information: | |
| Feedback required?: | No |
| Comments from Reviewer | |
| Cancel Comments: | Not Wood related |