

<b>Observation Number:</b>	201810255
<b>Originator:</b>	
<b>Date Created:</b>	18-Jul-2018
<b>Business Unit:</b>	AS EAAA
<b>Business Group:</b>	Operations Services Europe & Africa
<b>Project/Office:</b>	Western Gas Alliance
<b>Sub Business Group:</b>	Transmission & Distribution
<b>Site/Office Name:</b>	Western Gas Alliance 1855005/6
<b>Work Related or Non-Work Related Observation?:</b>	Work Related
<b>Exact Location or Project of Act/Condition/Safe Behaviour:</b>	Strongbow Road, Chepstow
<b>Observation Type:</b>	Unsafe Act
<b>Observer Name:</b>	Matthew Rees
<b>Observer Email Address:</b>	carl.jones@wwutilities.co.uk
<b>Stakeholder:</b>	Wood
<b>Observation Date:</b>	16-Mar-2018
<b>Observation Time:</b>	14:30
<b>Observation Close Date:</b>	18-Jul-2018
<b>Details of safety observation:</b>	Vac Ex driver onsite doesn't have correct paperwork - REF46
<b>Immediate action taken:</b>	Matt stopped them from working - gave them a Ref 46 document to complete, to allow him to carry on working. Matt asked if he had any Ref 46 documents and John said he didn't have any.
<b>Supporting Information:</b>	
<b>Feedback required?:</b>	No