

Observation Number:	201810037
Originator:	
Date Created:	16-Jul-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Sub Business Group:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Work Related or Non-Work Related Observation?:	Work Related
Exact Location or Project of Act/Condition/Safe Behaviour:	st helens road, swansea
Observation Type:	Unsafe Condition
Observer Name:	J Coombes
Observer Email Address:	trevor.clark@wwutilities.co.uk
Stakeholder:	Contractor
Observation Date:	05-Feb-2018
Observation Time:	14:30
Observation Close Date:	
Details of safety observation:	ISL: site visit, reinstatement was open on the opposite footway to a lane closure. In order to complete the works the footway was partially obstrcuted. Ask team to appoint a wathc out to prevent mop from stepping out into the oncoming traffic and direct them to the inside of the works.
Immediate action taken:	Carl warren became appointed marshall to directed mop.
Supporting Information:	
Feedback required?:	No
Comments from Reviewer	
Cancel Comments:	Not wood related