

Observation Number:	201808429
Originator:	
Date Created:	24-Jun-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Sub Business Group:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Work Related or Non-Work Related Observation?:	Work Related
Exact Location or Project of Act/Condition/Safe Behaviour:	Clifford Ave Kingswells Torquay
Observation Type:	Unsafe Condition
Observer Name:	Jason Miller
Observer Email Address:	john.dowson@wwutilities.co.uk
Stakeholder:	Wood
Observation Date:	17-Jan-2018
Observation Time:	10:30
Observation Close Date:	27-Jun-2018
Details of safety observation:	Jason Miller site visit :Team are trenching down the rd they have crossed a drive way , the team have used 3 heavy duty boards and pushed them together to allow vehicle access to the drive way
Immediate action taken:	Jason told the team to remove the boards and barrier off the trench and to inform the customer to leave the car off the drive way . FLM have been told to order rd plates and for them to be put in place
Supporting Information:	
Feedback required?:	No