

Observation Number:	201808466
Originator:	
Date Created:	25-Jun-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Sub Business Group:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Work Related or Non-Work Related Observation?:	Work Related
Exact Location or Project of Act/Condition/Safe Behaviour:	Murgwyn jct of Heol y Felin Rwibina
Observation Type:	Unsafe Condition
Observer Name:	Dean George
Observer Email Address:	carl.jones@wwutilities.co.uk
Stakeholder:	Wood
Observation Date:	19-Jan-2018
Observation Time:	12:15
Observation Close Date:	27-Jun-2018
Details of safety observation:	The team lifted slabs to dig out a connection hole to locate services and found a large BT cable under the slabs near the surface that had previously been damaged and looped around the excavation .
Immediate action taken:	The team used the air lance to expose the cable , lifted out the BT cable whilst digging out the hold and did safe digging practice
Supporting Information:	
Feedback required?:	No