

Observation Number:	201809250
Originator:	
Date Created:	03-Jul-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Sub Business Group:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Work Related or Non-Work Related Observation?:	Work Related
Exact Location or Project of Act/Condition/Safe Behaviour:	Nantgarw Road Caerphilly
Observation Type:	Unsafe Condition
Observer Name:	Ian Palmer
Observer Email Address:	carl.jones@wwutilities.co.uk
Stakeholder:	Wood
Observation Date:	27-Jan-2018
Observation Time:	09:15
Observation Close Date:	16-Jul-2018
Details of safety observation:	Went to fuse a 75 cap end and there was no copper connection point on the cap end to connect the leads. This came from the Stores and still in the bag. Again very poor quality fittings.
Immediate action taken:	T/L gave it to Tommy Richards to send back for investigation.
Supporting Information:	
Feedback required?:	No