

Observation Number:	201900420	
Originator:		
Date Created:	11-Jan-2019	
Business Unit:	AS EAAA	
Business Group:	Capital Projects EAAA	
Project/Office:	PREEM	
Service Line:	NEMEA	
Site/Office Name:	Amec FW / VGO Project PREEM	
Home or Work Related Observation?:	Work	
Exact Location or Project of Act/Condition/Safe Behaviour:	West side Pipe rack top floor.	
Observation Type:	Unsafe Condition	
Observer Name:	Kolliboina, Vamsi	
Observer Email Address:	vamsi.kolliboina@woodplc.com	
Stakeholder:	Wood	
Observation Date:	11-Jan-2019	
Observation Time:	10:30	
Observation Close Date:	05-Feb-2019	
Observation Category:	Work Environment Pedestrian routes (floors, stairs etc.)	
Details of safety observation:	The tarpaulin sheet spread on the top floor of the rack for protection from blasting is not secure in places and is coming off and can be a trip hazard for the workforce walking on it.	
Immediate action taken:		
Supporting Information:		
Feedback required?:	No	
Reasons for Amendment		
Comment	Entered By	Date Entered
Obs name	Paul Harrington	05-April-2019 11:23