

Observation Number:	201810245
Originator:	
Date Created:	18-Jul-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Sub Business Group:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Work Related or Non-Work Related Observation?:	Work Related
Exact Location or Project of Act/Condition/Safe Behaviour:	BT Fleet, Treforest
Observation Type:	Unsafe Condition
Observer Name:	Matthew Rees
Observer Email Address:	carl.jones@wwutilities.co.uk
Stakeholder:	Wood
Observation Date:	22-Feb-2018
Observation Time:	08:30
Observation Close Date:	18-Jul-2018
Details of safety observation:	Vehicle YE63 AGA went in BT for a sevice and and other issues with the vehicle to be fixed . The vehicle came out and the reversing camera still was not working
Immediate action taken:	BC contacted Donna at BT Fleet who checked the information with the work shop, the camera was not listed as being faulty , this has now been booked in 13th March 8.30
Supporting Information:	
Feedback required?:	No